335783

Appointment Day 05 Date 12 Time 09
Date Appointment Made _____

Customer _____

Address 836 Live Oak Dr

City Menlo Park State CA Zip _____

Phone(H) _____ (W) _____

Number of fireplaces? _____ Number of Chimneys? _____

BRACAMONTE
CHIMNEY SERVICE
1-408-440-0469
1-408-365-8136
Lic # 240706

CONDITION REPORT

Type of Fireplace: Prefab____ Masonry___
Fireplace Opening Size ____X___Flue___x____
Insert_____ Free Standing Stove_____
Brand Name_____

	Unsatisfactory	
	1st Chimney	2nd Chimney
CHIMNEY		
Chimney Cap		
Crown/Wash/Mortar Cap		
Bricks/Mortar Joints		
Flue Liner		
Moisture Resistance		
Flashing		
FIREPLACE		
Smoke Chamber		
Smoke Damage		
Damper		
Firebox		
Heat Reflector		
Loglighter		
Ash Dump/Clean Out Door		



Description	Cost	Work Ordered
Sweep/Inspection		79-
Smoke Test		
Video Inspection		
Regular Cap		99-
Special Cap		
Top Sealing Damper		
Flashing Repair		160-
Crown Repair		
New Crown		280-
Waterproofing		
Fire Box Repair		60-
Heat Reflector/Shield		
Fireplace Screen		
New Liner		
Tuckpoint Flue		
Repair Smoke chamber		
Smoke Guard		
Log Lighter		
Ash Dump Door		40-
Clean Out Door		
Dryer Vent Cleaning?		
Duct Cleaning?		
	Sales Tax	
	Total	$ 718-

Comments:

+$200 furniture move + dump
Paid $99 v# 1951
Paid $300 v# 330 Bal due → $519

Work Authorized By _____ Customer Signature

Sweep Signature _____

Date Of Next Appointment _____

Note: This sheet is a result of a visual inspection done at the time of cleaning. It is intended as a convenience to our customer, not as certification of fire worthiness or safety. Since conditions of use are beyond our control, we make no warranty of safety or function of any appliance and none is to be implied.